



STATE OF IDAHO

DEPARTMENT OF HEALTH
AND WELFARE

DIVISION OF ENVIRONMENT
Statehouse
Boise, Idaho 83720

ID 0961 4a
4.29.87

April 29, 1987

MEMORANDUM

TO: Steve Provant
FROM: Mark Torf ^{SL for}
SUBJECT: RCRA Compliance Inspection Report

Attached is a Hazardous Waste Management Act/RCRA Compliance Inspection Report for the Arrcom facility. Based on current Superfund activities, we are not planning to proceed with any RCRA enforcement action at this time.

Please contact me if you have any questions or concerns.

MT/jd

Attachment

USEPA RCRA



3009282

RCRA COMPLIANCE INSPECTION NARRATIVE REPORT

Date of Inspection:

March 18, 1987

Facility:

ARRCOM, Inc. (Drexler Enterprises, Inc.)

EPA Identification No.:

IDD000800961

Address:

Highway 53
3 miles west of Rathdrum
Rathdrum, Idaho 83858

Report Prepared By:

Scott Lund
Sr. Hazardous Materials Specialist
Division of Environment (DOE)
Department of Health and Welfare (IDHW)

Inspection Participants:

Steve Provant, EPA/Idaho Operations Office

Background Information:

ARRCOM, Inc. submitted a Part A RCRA Application to EPA on November 17, 1980 for on-site storage, treatment and/or disposal of hazardous waste. The facility initially qualified for interim status under RCRA to store and treat ignitable, corrosive, and spent solvent hazardous wastes. On June 20, 1982, an inspection conducted by EPA at the facility found that hazardous waste and/or hazardous waste constituents had been stored, spilled and/or disposed on-site.

An EPA Complaint and Compliance Order issued on April 27, 1983, required ARRCOM, Inc. to submit a Part B RCRA Permit